



TABEL DE MISCARE PARCELARE PENTRU DEZLIPIRE

SITUATIA ACTUALA (inainte de dezlipire)				SITUATIA VIITOARE (dupa dezlipire)			
Nr. cad.	Suprafata (mp)	Categoria de folosinta	Descrierea imobilului	Nr. cad.	Suprafata (mp)	Categoria de folosinta	Descrierea imobilului
230830	409	Cc	teren intravilan curti constructii	230830	188	Cc	Lot 1, 1/1Cc
Total	409			230830	221	Cc	Lot 2, 1/2Cc
				Total	409		

Verif/expert

Nume

Semnatura

Cerinta

Referat/expertiza nr./data


DUMYS ARHITECTURA S.R.L.

PUIU DANIEL ALIN SI PUIU GEORGETA
Mun. Craiova, Str. Ioan Cantacuzino, Nr. 12,
Bl. S21, Sc. 1, Ap. 6, Jud. DOLJ
DESFIINTARE CORP C1 SI
CONSTRUIRE LOCUINTA P+1E
Mun. Craiova, Str. Rasinari, Nr. 53, Jud. Dolj


PR. NR.
2 / 2022

FAZA:
D.T.A.C.



PLAN DE SITUATIE



FATADA SUD SCARA 1:100



FATADA NORD SCARA 1:100



ALTA PRAF DE PIATRA
ARIE DE LEMN
TOARE DE TABLA

Nume	Semnatura	Cerinta	Referat/expertiza nr./data	PR. NR.

PLAH
SITUATIE

717201

19.05.2022

07.2022

RUIRE

d. DOLJ

GETA


12, bl.

GETA


12, bl.

Ing. Barbu Gabriel Iulian

Desenat




FATADA EST SCARA1:100



FATADA VEST SCARA1:100

LA PRAF DE PIATRA
DE LEMN
ARE DE TABLA



K-01

PLAN FUNDATII

02.2022

Ing. Barbu Gabriel Mihai

Desenat

R A

717201

19.05.2022

07.2022

RUIRE

d. DOLJ

GETA

12, bl.

GETA

12, bl.

E